

Pioneer PX Series Balances Instruction Manual

Pioneer Balanzas Serie PX Manual de Instrucciones

Pionnier Balance de Séries PX Manuel d'instruction

Pioneer PX-Serie Waagen Bedienungsanleitung

Bilance Pioneer Serie PX Manuale di Istruzioni



## **REVISION HISTORY**

Date	Version	Description
May 6, 2023	L	<ul> <li>Added Formulation in 7.3 Printout Examples</li> <li>Added new models in 9.1 Specifications: PX12001</li> <li>Updated 9.2 Drawings and Dimensions</li> </ul>
Sep. 12, 2023	М	Updated US and China company address

# **Table of Contents**

1.	INTR	ODUCTION	.3
		Description	
	1.2 F	eatures	. 3
		Definition of Signal Warnings and Symbols	
		Safety Precautions	
2.	INST		.4
	2.1 L	Inpacking	. 4
	2.2 5	Select the Location	. 4
		eveling	
		Connecting Power and Acclimatising the Balance	
		Connecting the Interface	
		nitial Calibration	
3.		RATION	
		Overview of Display, Home Screen	
		Principal Functions and Main Menu	
		Overview of Parts and Features – Draft Shield Models	
_		Overview of Parts and Features – Non-Draft Shield Models	
4.		ICATIONS	
		Veighing	
		Parts Counting	
		Percent Weighing	
		Dynamic Weighing	
		Density Determination	
	4.5.1 4.5.2	Measuring the Density of a Sinking Solid Using Water	
	4.5.2 4.5.3	Measuring the Density of a floating Solid Using Water Measuring the Density of a Solid Using an Auxiliary Liquid other than Water	
	4.5.4	Measuring the Density of a Liquid Using a Calibrated Sinker	
	4.5.4	Measuring the Density of Porous Material Using Oil	
		ormulation	
		ditional Features	
5.		J SETTINGS	
•		/enu Navigation	
	5.1.1	Changing Settings	
		Calibration	
	5.2.1	Calibration Sub-menu (InCal models)	
	5.2.2	Internal Calibration (not applicable to ExCal models)	
	5.2.3	Automatic Calibration (PX85 PX125D PX225D ONLY)	23
	5.2.4	InCal Adjust (not applicable to ExCal models)	23
	5.2.5	Span Calibration	23
	5.2.6	Linearity Calibration	
		Balance Setup	
	5.3.1	Password	
	5.3.2	Language	
	5.3.3		
	5.3.4	AZT (Auto Zero Tracking)	
	5.3.5	Auto Tare	
	5.3.6		
	627	Graduations	
	5.3.7 5.3.8	Date Format	28
	5.3.8	Date Format Date Setup	28 28
	5.3.8 5.3.9	Date Format Date Setup Time Format	28 28 28
	5.3.8 5.3.9 5.3.10	Date Format Date Setup Time Format Time Setup	28 28 28 28
	5.3.8 5.3.9 5.3.10 5.3.11	Date Format Date Setup Time Format Time Setup Brightness	28 28 28 28 28
	5.3.8 5.3.9 5.3.10 5.3.11 5.3.12	Date Format Date Setup Time Format Time Setup Brightness Auto Dim	28 28 28 28 28 28
	5.3.8 5.3.9 5.3.10 5.3.11 5.3.12 5.3.13	Date Format Date Setup Time Format Time Setup Brightness Auto Dim Auto Off	28 28 28 28 28 28 29
	5.3.8 5.3.9 5.3.10 5.3.11 5.3.12 5.3.13 5.3.14	Date Format Date Setup Time Format Time Setup Brightness Auto Dim	28 28 28 28 28 28 29 29

	5.5 R	S232 Interface Setup	32
	5.5.1	Baud Rate	32
	5.5.2	Transmission	32
	5.5.3	Handshake	32
	5.6 P	rint Settings	32
	5.6.1	Stable Only	32
	5.6.2	Numeric Only	32
	5.6.3	Single Header	32
	5.6.4	Print To	32
	5.6.5	Output Format	33
	5.6.6	Batch Printing	33
	5.6.7	Label Printing	
	5.6.8	Auto Print	
	5.6.9	Header	33
	5.6.10	Date and Time	
	5.6.11	Balance ID	
	5.6.12	Balance Name	
	5.6.13	User Name	34
		Project Name	
		Application Name	
		Result	
	5.6.17	Gross	
	5.6.18	Net	
	5.6.19	Tare	
		Line Feed	
	5.6.21		
		LP	
	5.7.1	– Header	
	5.7.2	Balance Name	
	5.7.3	User Name	
	5.7.4	Project Name	
	-	actory Reset	
		ockout	
6		L FOR TRADE (LFT)	
0.	6.1 S	ettings	36
		erification	
		ecuring the Menu	
		ealing Access to the Balance Settings	
7.			37
1.			•••
		onnecting, Configuring and Testing the Printer / Computer Interface	
		utput Format	
_		rintout Examples	
8.		TENANCE	
		alibration	
		leaning	
		roubleshooting	
		ervice Information	
9.	TECH	NICAL DATA	43
	9.1 S	pecifications	43
	9.2 D	rawings and Dimensions	49
	9.3 A	ccessories	49
		ommunication	
	9.4.1	Interface Commands	
	9.4.2	RS232 (DB9) Pin Connections	
	9.4.3	USB Interface	
	9.4.4	USB Connection	
10	SOFT	WARE UPDATES	
			55

# **1.INTRODUCTION**

#### 1.1 Description

The PX balance is a precision weighing instrument that will provide you with years of service if properly cared for. PX balances are available in capacities from 82 grams to 8200 grams.

#### 1.2 Features

Operation Controls: 2-line backlit display, with 6 weighing applications and many other features.



#### 1.3 Definition of Signal Warnings and Symbols

Safety notes are marked with signal words and warning symbols. These show safety issues and warnings. Ignoring the safety notes may lead to personal injury, damage to the instrument, malfunctions and false results.

WARNING	For a hazardous situation with medium risk, possibly resulting in injuries or death if not avoided.
CAUTION	For a hazardous situation with low risk, resulting in damage to the device or the property or in loss of data, or injuries if not avoided.
Attention Note	For important information about the product For useful information about the product

#### Warning Symbols



**General Hazard** 



**Electrical Shock Hazard** 







**Alternating Current** 



**Direct Current** 

#### **Safety Precautions** 1.4



CAUTION: Read all safety warnings before installing, making connections, or servicing this equipment. Failure to comply with these warnings could result in personal injury and/or property damage. Retain all instructions for future reference.

- Verify that the AC adapter's input voltage range and plug type are compatible with the local AC main power supply.
- Make sure that the power cord does not pose a potential obstacle or tripping hazard.
- Do not position the balance such that it is difficult to reach the power connection.
- The balance is for indoor use only. Do not operate the equipment in hazardous or unstable environments.
- Operate the equipment only under ambient conditions specified in these instructions.
- Do not drop loads on the pan.
- Use the balance only in dry locations.
- Disconnect the equipment from the power supply when cleaning.
- Use only approved accessories and peripherals.
- Service should only be performed by authorized personnel.

# 2.INSTALLATION

# 2.1 Unpacking


Carefully remove your PX balance and each of its components from the package. The included components vary depending on the balance model (see the list below). Save the packaging to ensure safe storage and transport. Please read the manual completely before installing and using the PX balance to avoid incorrect operation.


Components included:

- Balance
- Power adapter + Attaching plug
- Stainless steel pan
- Pan support (for 0.1 g / 0.01 g model only)
- Warrenty card

# 2.2 Select the Location

Avoid heat sources, rapid temperature changes, air current or excessive vibrations. Allow sufficient space.









# 2.3 Leveling

Be sure the balance is level before it is used or after its location is changed.

The PX balance has a level bubble in a small round window beside the display.

To level the balance, adjust the 4 Leveling Feet until the bubble is centered in the circle. Please refer to Figure 2-1 for leveling.




Figure 2-1. Leveling

# 2.4 Connecting Power and Acclimatising the Balance

Connect the DC output connector to the power receptacle on the rear of the balance. Then connect the AC adapter plug to a suitable electrical outlet.

## Acclimatising

It is suggested that the balance should not be used until it has been connected to power and acclimatised to the environment for a certain period of time. In the case of a balance with the precision above 0.1 mg, the acclimatisation time should be 1.5 hours; in the case of balance with the precision of 0.01 mg, the acclimatisation time should be more than 4 hours.

# 2.5 Connecting the Interface

The PX balance has two data interfaces, RS232 and USB.

Use the RS-232 port to connect either to a computer or a printer with a standard (straight-through) serial cable. Use the USB port to connect to a computer with a USB 2.0 Type A to Type B cable.

Interface connections on the rear of the balance



USB: Used to connect to PC only

RS232: Used to connect to PC or Printer

Note: For Connecting, Configuring and Testing the Printer / Computer Interface, see the Printing section.

# 2.6 Initial Calibration


When the PX balance is first installed, or when it is moved to another location, it must be calibrated to ensure accurate weighing results. PX balances are classified into two categories, InCal models and ExCal models. InCal models have a built-in calibration mechanism which can calibrate the balance automatically and does not require the use of external calibration masses. If preferred, InCal models can also be manually calibrated with external masses. ExCal models are calibrated with external masses. Make sure to have the appropriate calibration masses available before beginning calibration.

# **3.OPERATION**

# 3.1 Overview of Display, Home Screen

The PX balance has a 2-line backlit display.

## CONTROLS



#### **CONTROL FUNCTIONS**

Button	Zero U Yes	Print Unit No	Function Mode Back	Tare Menu-Cal Exit
Primary Function (Short Press)	<ul> <li>On / Zero</li> <li>If the Indicator is Off, turns on the Indicator.</li> <li>If Indicator is On, sets zero.</li> </ul>	<ul> <li>Print</li> <li>Sends the current displayed value to the serial interface.</li> </ul>	<ul> <li>Function</li> <li>Operation is dependent on the application mode.</li> </ul>	Tare <ul> <li>Performs tare operation.</li> </ul>
Secondary Function (Press and Hold)	Off • Zeroing current value.	Unit <ul> <li>Changes weighing units.</li> </ul>	Mode <ul> <li>Changes         application mode.     </li> </ul>	<ul> <li>Menu-Cal</li> <li>Enters the main menu. Calibration is the first sub-menu.</li> <li>Views the preset Tare value.</li> </ul>
Menu Function (Short Press)	Yes <ul> <li>Accepts the current (blinking) setting on the display.</li> </ul>	<ul> <li>No</li> <li>Rejects the current (blinking) setting on the display.</li> <li>Increments a value being entered.</li> </ul>	<ul> <li>Back</li> <li>Reverts back to previous menu item.</li> <li>Decrements a value being entered.</li> </ul>	<ul> <li>Exit</li> <li>Immediately exits the sub- menu.</li> <li>Aborts a calibration in progress.</li> </ul>

### MAIN APPLICATION SCREEN



## 3.2 Principal Functions and Main Menu


Weighing: Press **Zero** to set the display to zero. Place an object on the pan. The display indicates the gross weight.

Taring: With no load on the pan, press **Zero** to set the display to zero. Place an empty container on the pan and press **Tare**. Add material to the container and its net weight is displayed. After the container and the objects are removed, the load will be displayed as a negative number. Press **Tare** to clear.


Zero: Press **Zero** to zero the balance.

Dot-matrix The relevant data in the specific application mode are shown in the dot-matrix display area. Display:

## 3.3 Overview of Parts and Features – Draft Shield Models



## 3.4 Overview of Parts and Features – Non-Draft Shield Models



# **4.APPLICATIONS**

The PX balance can be operated in 6 application modes by long pressing the **Function / Mode** button.

## 4.1 Weighing

Note: Before using any application, be sure the balance has been leveled and calibrated.

Use this application to determine the weight of objects in the selected unit of measure.

#### Weighing

1.	Press Tare or Zero if necessary to begin.					
2.	Press and hold the <b>Function / Mode</b> button to select <i>Weighing</i> (this application is the default).					MODE
3.	Place objects on the pan to display the weight. Once the reading is stable, the * will appear.		Weigh	ning		HODE
4.	The resulting value is displayed in the active unit of					<b>PIONEER</b> <sup>™</sup>
	measure.	[	Zero U Yes	Print Unit No	Function Malm Ba	Tare Menu-Cal Exit
Item Se	ettings	1				

To view or adjust the current settings.

- **Capacity Bar:** When set to On, the capacity bar is displayed in the reference field. The capacity will not display when the balance is set to zero.
- Weighing Units: Change the displayed unit. See Section 5.4 for more information.
- Filter Level: Change Filtering level. See Section 5.3.2 for more information.
- GLP Data: See Section 5.7 for more information.
- Print Settings: Change printing settings. See Section 7 for more information.


# Batch Weighing

To enable batch weighing.	
1. Press and hold the <b>Menu-Cal</b> button until <b>Calibration</b>	
appears.	
2. Short press the No button several times until Print	
appears.	MENU
3. Press the <b>Yes</b> button.	Calibration
4. Short press the <b>No</b> button several times until <b>Batch</b>	PIONEER
Printing appears.	
	Zoro 🕐 Print Function Tare
5. Press the <b>Yes</b> button.	Zero Unit Mode Menunat

#### **PX Series Balance**

#### To start batch weighing:


- 1. Re-enter the **Weighing** mode. Place the first sample on the pan and press the **Function / Mode** button to store the first weight.
- 2. Then, the message "Place sample 2" will display.
- 3. Remove the first sample, add the second sample to the pan, and press the **Function / Mode** button to store the second weight.
- Continue adding components, and press the Function / Mode button to store the weights.



To end batch weighing and print the result:

Press the **Print** button to end batch weighing and print the result. **Note**: a total of 10 batch of samples can be weighed. When 10 is reached, the message "**End**" will display if

the **Function / Mode** button is pressed again. If continue to press the button, the message "**Out of range**" will display.





## 4.2 Parts Counting

**Note:** Before using any application, be sure the balance has been leveled and calibrated. The minimum piece weight should be no less than 0.1d. In the LFT mode, the minimum piece weight is 3e, the minimum Sample Size is 10.

Use this application to count samples of uniform weight.

#### Parts Counting





Item Settings

<ul><li>Sample: The sample size ranges from 1 to 1000. The default value is 10.</li><li>Note: To ensure accurate counting, the minimum piece weight should be no less than 0.1d.</li></ul>	Clear APW?
	PIONEER <sup>™</sup> Zero <sup>(1)</sup> Yes No Function Mode Menu-Cal Back Exit

### APW Optimization:

Improving counting accuracy by re-calculating the piece weight automatically as parts are added.

APW Optimization occurs only when the number of pieces added to the pan is between one and three times the number already on the pan.

#### **Print Settings:**

Changing printing setup. See Section 7 for more information.


## 4.3 Percent Weighing


Note: Before using any application, be sure the balance has been leveled and calibrated.


Use Percent Weighing to display the weight of a test object as a percentage of a pre-established reference sample.

The default (or last) reference weight is displayed.

#### **Percent Weighing**







#### **Printing Setup:**

displays.

Changing printing setup. See Section 7 for more information.

Clear	referenc	e?	
			<b>PIONEER</b> <sup>™</sup>
Zero U	Print Unit No	Function Mode Back	Tare Menu-Cal Exit


## 4.4 Dynamic Weighing

**Note:** Before using any application, be sure the balance has been leveled and calibrated. Clear the pan before beginning a new Dynamic Weighing cycle.

Use this application to weigh an unstable load, such as a moving animal.

#### **Dynamic Weighing**

1.	Press and hold the <b>Function / Mode</b> button until <i>Dynamic Weighing</i> appears.	
2.	After confirmation by pressing <b>Yes</b> , the message "Change parameter?" will appear on the screen.	MODE Dynamic Weighing
		PIONEER
		Zero Drint Unit Modern Menu-Cal
3.	Press <b>Yes</b> , and then the message "Average time 10 s" will display with the numeral "10" flashing. Press <b>No</b> or <b>Back</b> to increase or decrease the value as desired.	
		Average time 10 s
		PIONEER
		Zero Yes



Item Settings

- 1. Averaging Time: Set the averaging time to a value between 1 and 15 seconds. Default is 10 seconds.
- 2. Printing Setup: Changing printing setup. See Section 7 for more information.

# 4.5 Density Determination

Note: Before using any application, be sure the balance has been leveled and calibrated.

Use this application to determine an object's density.

A **Density Determination Kit, Part Number 80253384,** is designed to be used with PX series balances. Illustrations in this procedure refer to the density kit, however, you may use whatever lab apparatus that will suit the requirements for density measurements. A built in reference density table for water at temperatures between 10°C and 30.9°C is included in the balance software. Review this entire section before attempting density measurements.

#### **Operation Method**

Press and hold the Function / Mode button until the Density appears on the screen.

After confirmation by pressing **Yes**, the message "Change parameter?" will display on the screen. The settings can be kept or changed as desired.

#### Item Settings:

- Sample Type: Solid, Liquid
- Auxiliary Liquid: Water, Alcohol, Other
- Porous Material: Off, On
- Water Temperature: 20°C (by default)
- Alcohol Temperature: 20°C (by default)
- Volume (of Calibrated Sinker): 10 ml (by default)
- Weight (of Porous Material): 5.000 g

- Oil Density: 0.80000 g / cm<sup>3</sup>
- Result: to select the display resolution of Density's weighing result.
  - 0.01mg balance model: 0.1g/cm<sup>3</sup>, 0.01g/cm<sup>3</sup>, **0.001g/cm**<sup>3</sup>, 0.0001g/cm<sup>3</sup>, 0.00001g/cm<sup>3</sup>
  - 0.1mg balance model: 0.1g/cm<sup>3</sup>, 0.01g/cm<sup>3</sup>, 0.001g/cm<sup>3</sup>, 0.0001g/cm<sup>3</sup>
  - 1mg balance model: 0.1g/cm<sup>3</sup>, 0.01g/cm<sup>3</sup>, **0.001g/cm<sup>3</sup>**
  - 0.01g balance model: 0.1g/cm<sup>3</sup>, 0.01g/cm<sup>3</sup>
  - 0.1g balance model: **0.1g/cm<sup>3</sup>**

Four types of density determination can be made:


- 1. Solid more density than the auxiliary liquid
- 2. Solid less density than the auxiliary liquid
- 3. Liquid density

the water temperature value entered.


4. Porous material (impregnated with oil)

The following are the operating procedures for determining density of solid, liquid and porous material with water as the auxiliary liquid. Other auxiliary liquids are also applicable for density determination.

## 4.5.1 Measuring the Density of a Sinking Solid Using Water



#### **PX Series Balance**



## 4.5.2 Measuring the Density of a floating Solid Using Water


1. Press and hold the <b>Functio</b> appears. Press <b>Yes</b> to enter	<b>n / Mode</b> button until <i>Density</i> the <i>Density Determination</i> .	Density	 Mode
			PIONEER"
		Zero Yes	Function Mode Back Henu-Cal
setup and density determina the same for a floating so except for the necessary ho to be used for density determ	press the Function / Mode		
<b>Note:</b> Lower the sample down submerged.		Holder for non-floating solids	g Holder for floating solids

1.	Press and hold the <b>Function / Mode</b> button until <i>Density</i> appears. Press <b>Yes</b> to enter the <i>Density Determination</i> .	MODE Density PIONEER*
		Zero Yes No Function Mode Menu-Cal Exit
Iten	n Settings:	
	Sample type: Solid	
	Auxiliary Liquid: Other	
	Porous Material: Off	Liquid Other
		PIONEER"
		Zero Unit Function Mode Menu-Cal
Set	the density of the auxiliary liquid:	
2.	The default value of the auxiliary liquid is 1.00000 g/cm <sup>3</sup> .	
3.	Press <b>No</b> or <b>Back</b> to increase or decrease the value in accordance with the actual density of the auxiliary liquid.	1.00000 g/cm <sup>3</sup>
		PIONEER
		Zero Unit Unit No Back Exit
4.	See Section 4.5.1 and Section 4.5.2 for the specific procedures for density determination.	10007
5.	Press the <b>Function / Mode</b> button to display the density of the sample.	<b>I.]]] I</b> g/cm <sup>3</sup>
6.	After completion of the test, press the <b>Function / Mode</b> button to test a new sample.	PIONEER"
		Zero     Print Unit     Function Mode Back     Tare Menu-Cal       '     '     '


# 4.5.3 Measuring the Density of a Solid Using an Auxiliary Liquid other than Water


# 4.5.4 Measuring the Density of a Liquid Using a Calibrated Sinker

Press and hold the <b>Function / Mode</b> button until <i>Density</i> appears. Press <b>Yes</b> to enter the <i>Density Determination</i> .	MODE Density PIONEER <sup>™</sup> Zero <sup>(*)</sup> <u>Zero <sup>(*)</sup></u> <u>Print</u> Unit <u>Modern</u> <u>Tare</u> Menu-Cal
<b>Item Settings:</b> Sample Type: Liquid Volume: The calibrated sinker has a default volume of 10.0 ml, which can be increased or decreased by pressing <b>No</b> or <b>Back</b> .	Yes No Back Exit Type Liquid PIONEER <sup>™</sup> Zero Print Unit Function Mode Tare Menu-Cal
After setting the volume, press <b>Yes</b> to begin the weighing. <b>Note:</b> when the Density Type is set to Liquid, the Liquid type and Porous material selections are disabled.	Ves No Back Exit Volume 10.0 ml PIONEER Zero Volume 10.0 ml Exit
<ol> <li>Weigh the calibrated sinker in the air with the balance and the density determination kit.</li> <li>When the * (symbol of stability) appears, press the Function / Mode button to confirm the weight of the calibrated sinker in the air.</li> </ol>	* GGGGGGGGGGGGGG In air Pioneer Zero Yes No Function Mode from Back Tare Menu-Cal Exit



## 4.5.5 Measuring the Density of Porous Material Using Oil







## 4.6 Formulation

Note: Before using any application, be sure the balance has been leveled and calibrated.

Use this application for compounding and recipe making. The maximum number of components is 50.

#### Formulation






## 4.7 Additional Features

#### Weigh Below

Note: Ensure the balance has been leveled and calibrated.

The PX balance is equipped with a weigh below hook for weighing below the balance (as shown in the figure below).



Before turning the balance over, remove the pan and draft shield elements (if present) to prevent damage. Do not place the balance on the pan support cone or load cell pins.

To use this feature, remove power from the balance, then remove the protective cover for the weigh below opening.

Power on the balance, and then use a string or wire to attach items to be weighed.



# **5.MENU SETTINGS**

# 5.1 Menu Navigation

#### TABLE 5-1. USER MENU STRUCTURE

Calibration	Setup	Units	RS232	Print	GLP	Factory Reset	Lockout
Internal Cal	Password	Gram	Baud Rate	Stable Only	Header 1	Reset All	Calibration
Automatic Cal	Language	Kilogram	Transmission	Numeric Only	Header 2		Setup
Span Cal	Filter Level	Milligram	Handshake	Single Header	Header 3		Units
Linearity Cal	AZT	Carat		Print To	Header 4		RS232
InCal Adjust	Auto Tare	Newton		Auto Print	Header 5		Print
	Graduations	Pound		Output Format	Balance Name		GLP
	Date format	Ounce		Batch Printing	User Name		Factory Reset
	Date	Ounce Troy		Label Printing	Project Name		
	Time Format	Grain		Header			
	Time	Pennyweight		Date and Time			
	Brightness	Momme		Balance ID			
	Auto Dim	Mesghal		Balance Name			
	Auto Off	Hong Kong Tael		User Name			
	Capacity Bar	Singapore Tael		Project Name			
	Approved Mode	Tanwan Tael		Application Name			
		Tical		Result			
		Tola		Gross			
		Baht		Net			
		Custom unit		Tare			
			•	Signature			
				Line			
				Line Feed			

Note: PX balances are classified into InCal models and ExCal models.

## 5.1.1 Changing Settings

To change a menu setting, navigate to that setting using the following steps:

#### Enter the Menu

Long press the Menu button to enter the **Menu**.

#### Select the Sub-Menu

Press No to step between the sub-menus, and press Yes to enter the sub-menu.

#### Select the Menu Item

Press No to step through the Menu Items, and press Yes to enter the displayed Menu Item.

## 5.2 Calibration

PX balances offer a choice of three calibration methods: Internal Calibration (for InCal models only), Span calibration and Linearity Calibration.

Attention: Do not disturb the balance during any calibration.

## 5.2.1 Calibration Sub-menu (InCal models)

Note: ExCal models only have Span Calibration and Linearity Calibration.

## 5.2.2 Internal Calibration (not applicable to ExCal models)

Calibration is accomplished with the internal calibration mass. Internal Calibration can be performed at any time, provided the balance has warmed up to operating temperature and is level.

With the Balance turned ON and no load on the pan, the internal calibration can be performed.

Alternatively, press the Tare / Menu-Cal button and select Internal Cal to initiate the internal calibration.

The screen shows the status, and then press any button to return to the current application after calibration.

## 5.2.3 Automatic Calibration (PX85 PX125D PX225D ONLY)

When **Automatic Calibration** is set ON, the balance performs a self calibration:

- when it senses a temperature change of 1.5°C
- or every 3 hours

AutoCal will automatically calibrate the Balance (using the internal mass) each time there is a change in temperature significant enough to affect accuracy.

## 5.2.4 InCal Adjust (not applicable to ExCal models)

Use this calibration method to fine tune the effect of the Internal Calibration. Calibration Adjust may be used to adjust the result of the Internal Calibration by  $\pm 100$  divisions.

**Note:** Before making a calibration adjustment, perform an Internal Calibration. To verify whether an adjustment is needed, place a test mass equal to the **span calibration value** on the pan and note the difference (in divisions) between the nominal mass value and the actual balance reading. If the difference is within +/- division, calibration adjustment is not required. If the difference exceeds +/-1 division, calibration adjustment is recommended.

Example:

Expected weight reading:	200.000 (Test mass value)
Actual weight reading:	200.014
Difference in gram:	- 0.014
Difference in division:	– 14 (InCal Adjust value)

To perform a Calibration Adjustment, select InCal Adjustment from the list of Calibration Menu; enter the value (positive or negative divisions) to match the difference noted earlier in the procedure.

Recalibrate using Internal Calibration. After calibration, place the test mass on the pan and verify that the mass value now matches the displayed value. If not, repeat the procedure until Internal Calibration reading agrees with the test mass.

Once completed, the balance stores the Adjustment value and the display returns to the current application.


## 5.2.5 Span Calibration

Span calibration uses two calibration points, one at zero load and the other at specified full load (span). For detailed calibration mass information, please see the specification tables in section 9.1.

With the balance turned ON and no load on the pan, Span Calibration can be performed. The best accuracy is achieved using the mass closest to the full span value.

## Steps for span calibration

<ol> <li>Press and hold the Tare / Menu-Cal button, and the Calibration Menu will display.</li> </ol>	MENU Calibration PIONEER <sup>**</sup> Zero Division Yes No Back Tare Menu Back Ex
<ol> <li>Press Yes to enter the Calibration Menu. To change the calibration mode, press No until Span Cal (span calibration) is displayed.</li> </ol>	CAL Internal Cal Pioneer Zero Print View No Back Tare Mode Back Exit
3. Press <b>Yes</b> to begin the span calibration.	CAL Span Cal PIONEER <sup>™</sup> Zero Unit Yes Mode Back Tare Menu-Cal Exit
4. The calibration masses value will be shown in the screen. After the display shows "Place weights" and "100.000 g", place weight(s) of 100 g on the pan for calibration. To change to the calibration point of half full capacity (e.g. 50 g), press the Function / Mode button. After the screen shows "Place weights" and "50.000 g", place weight(s) of 50 g on the pan for calibration.	Place weights Place weights Print Unit Yes Print Unit No Print Bac
5. Remove the weight from the pan.	Remove weights PIONEER"



## 5.2.6 Linearity Calibration

Linearity calibration uses three calibration points, one at zero load and the others at specified loads.

For detailed calibration mass information, please see the specification tables in section 9.1. With no load on the scale, Linearity Calibration can be performed. The balance captures the zero point, and then prompts for the next weight. Continue to follow the instructions on the display until the calibration is completed.

#### Steps for linearity calibration

1.	Press and hold the <b>Tare / Menu-Cal</b> button, and the Calibration Menu will display.	MENU Calibration Pioneer Zero Yes Yes
2.	Press <b>Yes</b> to enter the Calibration Menu. To change the calibration mode, press <b>N</b> o until Linearity Cal (linearity calibration) is displayed.	CAL Internal Cal PIONEER <sup>~</sup> Zero Yes Print Unit No Different Back Tare Menu-Cal Exit
3.	Press <b>Yes</b> to begin the linearity calibration.	CAL Linearity Cal PIONEER <sup>~~</sup> Zerg b Vinit Vinit No Back Tare Menu-Cal Exit

4.	Calibration masses value will be shown in the screen. After the display shows "Place weights" and "50.0000 g", place weight(s) of 50 g on the pan for calibration.	<b>SSILLIO</b> g Place weights <b>PIONEER</b> *
5.	Remove the weight(s) of 50 g from the pan. After a while, "100.0000 g" will be displayed on the screen. Please place weight(s) of 100 g on the pan for calibration.	Place weights
6.	Once the linearity calibration is completed successfully, "Linearity done" will display. Press any button to return to the previous screen.	Linearity done

## 5.3 Balance Setup

Enter this sub-menu to customize balance functionality. **Note:** The factory default settings are shown below in bold.

## 5.3.1 Password

#### Entering the password:

The password should be a combination of 1, 2 and 3 with the maximum length of 6 digits.

Button	Zero U Yes	Print Unit No	Function Mode Back	Tare Menu-Cal Exit
Numeric/Function 1 / Confirm		2 / Cancel	3	Instructional message "Do you confirm?"

For example, if the user wants to set the password as "132", the following steps should be taken:

- 1. First press Zero / Yes, then Function / Mode, and Print / Unit at last.
- 2. Press Tare / Menu, and the message "Do you confirm?" will appear on the screen.
- 3. Press Yes or No to confirm or cancel the password input.

# When the Password is set On and the password is not correctly entered, the menu settings are affected as follows:

#### Calibration Menu:

Auto Calibration, InCal Adjustment, Span Calibration and Linearity Calibration are locked at the current settings.

#### **PX Series Balance**

#### • <u>Setup Menu:</u>

Language, Filter level, Auto Zero Tracking, Auto Tare, Graduations, Date Format, Date Setting, Time Format and Time Setting are locked at the current settings.

• <u>Units Menu:</u>

All settings are locked.

• <u>Print Menu:</u> All settings are locked.

• <u>GLP Menu:</u> All settings are locked.

• Factory Reset Menu:

All settings are locked.


• <u>RS232 Menu:</u>

All settings are locked.

## 5.3.2 Language

Set the language displayed for menus and displayed messages.

English Deutsch Français Italiano Polski Español Türkçe Português 한국 中文 日本語



## 5.3.3 Filter Level

Set the amount of signal filtering.

Low	= faster stabilization time with less stability.
Medium	= normal stabilization time with normal stability.
High	= slower stabilization time with more stability.

Note: For 0.01mg balance model, the default is High.

## 5.3.4 AZT (Auto Zero Tracking)

Set the automatic zero tracking functionality.

Off = disabled.
0.5 d = display maintains zero up to a drift of 0.5 graduation per second.
1 d = display maintains zero up to a drift of 1 graduation per second.
3 d = display maintains zero up to a drift of 3 graduations per second.

## 5.3.5 Auto Tare

Set the automatic tare.

**Off** = disabled.

On = enabled.

 $\ensuremath{\textbf{Note:}}$  "Place container" will be displayed when Automatic Tare is set to On.

## 5.3.6 Graduations

Set the displayed readability of the balance.

#### 1 Division = standard readability.

10 Divisions = readability is increased by a factor of 10.

For example, if the standard readability is 0.01g, selecting 10 Divisions will result in a displayed reading of 0.1 g.

## 5.3.7 Date Format

Set the current date format.

YYYY/MM/DD **MM/DD/YYYY** DD/MM/YYYY

## 5.3.8 Date Setup

Set the date in the current date format. For example, if the date format is MM/DD/YYYY, the date could be set as "06/22/2017 Thu".

## 5.3.9 Time Format

Set the current time format.

**24HR** 12HR

## 5.3.10 Time Setup

Set the time in the current time format.

For example, if the time format is 24HR, the time could be set as 08:00:00.

## 5.3.11 Brightness

Set the brightness of the display.

Low **Medium** High

## 5.3.12 Auto Dim

Set whether the balance automatically turns off the display backlight of the display.

Off = disabled

10 minutes = become dim if there is no motion for 10 minutes

20 minutes = become dim if there is no motion for 20 minutes

30 minutes = become dim if there is no motion for 30 minutes

## 5.3.13 Auto Off

#### Off = disabled

30 minutes = turns off if there is no motion for 30 minutes 1 hour = turns off if there is no motion for 1 hour 2 hours = turns off if there is no motion for 2 hours

### 5.3.14 Capacity Bar

Off = disabled

#### On = enabled

When the capacity is set On, a capacity bar will display at the bottom of the screen. The capacity bar will roughly show the current weight as a percentage of balance capacity. When the display is at zero, the capacity bar will not display.

### 5.3.15 Approved Mode

Use this menu to set the Legal for Trade status.

#### Off = standard operation.

On = operation complies with Legal Metrology regulations.

Note: When Approved Mode is set to On, the menu settings are affected as follows:

#### Calibration Menu:

• For InCal models, only Internal Calibration is available. All other functions are hidden.

#### Balance Setup Menu:

- Filter Level is locked at the current setting.
- Auto Zero Tracking is limited to 0.5 Division and Off. The selected setting is locked.
- Auto Tare is locked at current setting.
- Graduations are forced to 1 Division and the menu item is hidden.

#### Communication Menu (Communication->Print Settings->Print Output):

- Stable Weight Only is locked On.
- Numeric Value Only is locked Off.

#### Communication Menu (Communication->Print Settings->Auto Print):

• Auto print mode selections are limited to Off, On Stability, and Interval. Continuous is not available.

#### Lockout Menu:

• Menu is hidden

**Note:** The security switch located at the rear of the balance must be in the locked position to set Approved Mode to On. The security switch must be in the unlocked position to set Approved Mode to Off. See Section 6.

# 5.4 Weighing Units

Enter this sub-menu to activate the desired units of measure.

PX balances provide a choice of 19 units, which are all set On by default. **Note:** Due to national laws, the balance may not include some of the units of measure listed.

Display	Unit
g	Gram
kg	Kilogram
mg	Milligram
ct	Carat
Ν	Newton
lb	Pound
oz	Ounce
ozt	Troy ounce
GN	Grain

Display	Unit	
dwt	Pennyweight	
mo	Momme	
msg	Mesghal	
tl H	HK tael	
tl S	SG tael	
tl T	TW tael	
tcl	Tical	
tola	Tola	
baht	Baht	
C1	Custom unit	

## **Changing Weighing Units**

1.	Press and hold the <b>Print / Unit</b> button until the <i>Unit Menu</i> is displayed.	* [][[]]][]]] g
		Zero     Print     Function     Tare       Yes     No     Back     Exit
2.	The default unit is gram (g). To change the unit, press <b>No</b> to advance to the next unit.	
		Units
		Gram
		<b>PIONEER</b> <sup>™</sup>
		Zero Yes Print Unit No No Function Mode Back Tare Menu-Cal
3.	Press <b>Yes</b> to set the unit displayed to the weighing unit.	
		Units Milligram
		PION€€R <sup>™</sup>
		Zero Unit Function Mode Menu-Cal

### **Defining Custom Unit**

Set Custom to On in the Unit menu to enable and define the Custom Unit.

The Custom Unit is defined by entering three parameters, Factor, Exponent and LSD (least significant digit). Define the Custom Unit as follows:

- 1. Determine how many custom units there are in 1 gram.
- 2. Convert the value to scientific notation, e.g. m x 10n.
- 3. Enter the value of m as the Factor setting.
- 4. Enter the value of n as the Exponent setting.
- 5. Enter the amount that the Custom Unit steps by as the LSD setting.

Enter the Factor and the Exponent and LSD.

Factor	Exponent (+3 to -3)	Conversion Factor
.1234	3	123.4
.1234	2	12.34
.1234	]	1.234
.1234	0	.1234
.1234	-1	.01234
.1234	-2	.001234
.1234	-3	.0001234

Custom Unit = Conversion Factor x Grams.

The LSD is the value by which the displayed weight is incremented or decremented.

LSD	Result
.5	Adds one decimal place
	Display counts by 5
]	Display counts by 1
2	Display counts by 2
5	Display counts by 5
10	Display counts by 10
100	Display counts by 100
	2.000.00

#### Note:

The conversion factor is used by the balance to convert grams to the custom weighing unit and is defined by entering a factor and an exponent. The factor is a value between 0.1000000 and 1.999999 inclusive. For example: One cup of chemical =  $0.5643834 \times 1$  g, the factor should be set 0.5643834.

The exponent moves the decimal point of the factor to the right for positive values or to the left for negative values. For example: One cup of chemical = 10 g, the exponent should be set <u>2</u>.

The LSD is the value by which weight is incremented or decremented.

LSD	Result
1	Display counts by 1
5	Display counts by 5
10	Display counts by 10

For example, if the displayed digital is 0.56 for one cup of chemical, the LSD should be set <u>100</u>.

## 5.5 RS232 Interface Setup

Enter this sub-menu to customize RS232 standard settings. Data may be output to either a printer or a PC.

#### 5.5.1 Baud Rate

Set the baud rate (bits per second).

- 1200 = 1200 bps
- 2400 = 2400 bps
- 4800 = 4800 bps
- 9600 = 9600 bps
- 19200 = 19200 bps
- 38400 = 38400 bps

### 5.5.2 Transmission

Set the data bits, stop bit, and parity.

8-NO-1	= 8 data bits, no parity, stop bit 1
8-NO-2	= 8 data bits, no parity, stop bit 2
7-EVEN-1	= 7 data bits, even parity, stop bit 1
7-EVEN-2	= 7 data bits, even parity, stop bit 2
7-NO-1	= 7 data bits, no parity, stop bit 1
7-NO-2	= 7 data bits, no parity, stop bit 2
7-0DD-1	= 7 data bits, odd parity, stop bit 1
7-ODD-2	= 7 data bits, odd parity, stop bit 2

## 5.5.3 Handshake

Set the flow control method.

None	= no handshaking
Xon-Xoff	= XON/XOFF handshaking
Hardware	= hardware handshaking

## 5.6 Print Settings

Enter this sub-menu to customize data transfer settings.

#### 5.6.1 Stable Only

**Off = values are printed immediately, regardless of stability.** On = values are printed only when the stability criteria are met.

#### 5.6.2 Numeric Only

**Off = All selected results are printed.** On = Only numeric data values are printed.

#### 5.6.3 Single Header

**Off = Headers will be printed for every print requirement.** On = Headers will be printed once a day.

## 5.6.4 Print To

PC = print data to a PC Printer = print data to a printer

#### 5.6.5 Output Format

Select to use which format to print: OHAUS – PX SICS: the Mettler Toledo format. ST: the Sartorius format. OHAUS – AR OHAUS – PA

#### 5.6.6 Batch Printing

**Off = Disable batch printing.** On = Enable batch printing. **Note**: for how to use batch weighing, please refer to the **Weighing** section for details.

#### 5.6.7 Label Printing

#### Off = Disable label printing.

On = Enable label printing.

There is 1 built-in label template:

- 100mm x 75mm, which is designed based on label size "100mm x 75mm". This template includes all basic information "Data/Time", "Balance Name", "Balance ID", "Gross Weight", "Tare Weight", "Net Weight", and "Signature".

The template can be edited via OHAUS Label Designer. Please go to the website below to download the software. https://dmx.ohaus.com/WorkArea/DownloadAsset.aspx?id=28916

For how to use the software, please contact an authorized dealer to obtain the software's instruction.

#### 5.6.8 Auto Print

Off

On Stability1= printing occurs each time the stability criteria are met.Print Interval2= printing occurs at the defined time interval.Continuous= printing occurs continuously.

<sup>1</sup>When On Stability is selected, set the conditions for printing.

#### Load = Prints when the displayed load is stable.

= disabled

Load and Zero = Prints when the displayed load and zero readings are stable.

<sup>2</sup>When Print Interval is selected, set the time interval using the numeric keypad.

Settings of 1 to 3600 seconds are available. Default is 0.

#### 5.6.9 Header

On = the header is printed.

Off = the header is not printed.

#### 5.6.10 Date and Time

On = the date and the time are printed.

Off = neither the date nor the time is printed.

#### 5.6.11 Balance ID

On = the balance ID is printed.

Off = the balance ID is not printed.

#### 5.6.12 Balance Name

**On = the balance name is printed.** Off = the balance name is not printed.

5.6.13 User Name

**On = the user name is printed.** Off = the user name is not printed.

#### 5.6.14 Project Name

On = the project name is printed.

Off = the project name is not printed.

#### 5.6.15 Application Name

**On = the application name is printed.** Off = the application name is not printed.

#### 5.6.16 Result

**On = the weighing result is printed.** Off = the weighing result is not printed.

#### 5.6.17 Gross

**On = the gross weight is printed.** Off = the gross weight is not printed.

#### 5.6.18 Net

**On = the net weight is printed.** Off = the net weight is not printed.

#### 5.6.19 Tare

**On = the tare weight is printed.** Off = the tare weight is not printed.

#### 5.6.20 Line Feed

1 Line = move the paper up one line after printing.4 Lines = move the paper up four lines after printing.

#### 5.6.21 Signature Line

On = the Signature Line is printed. Off = the Signature Line is not printed.

## 5.7 GLP

Enter this menu to set the Good Laboratory Practices (GLP).

#### 5.7.1 Header

Enables the printing of GLP headings. There are up to 5 headings available. Alphanumeric settings up to 25 characters are available for each Header setting

#### 5.7.2 Balance Name

Set the balance name. Alphanumeric settings up to 16 characters are available.

### 5.7.3 User Name

Set the user name. Alphanumeric settings up to 16 characters are available. The default is blank.

#### 5.7.4 Project Name

Set the project name. Alphanumeric settings up to 16 characters are available. The default is blank.

## 5.8 Factory Reset

Use this sub-menu to reset the all menu settings to their Factory default settings.

Reset All = resets all menus to their factory default settings. Exit = return to application main screen without resetting any menus.

## 5.9 Lockout

Use this sub-menu to lock/unlock certain menus.

#### **Off = the menu is unlocked** On = the menu is locked

## 6.LEGAL FOR TRADE (LFT)

When the balance is used in trade or a legally controlled application it must be set up, verified and sealed in accordance with local weights and measures regulations. It is the responsibility of the purchaser to ensure that all pertinent legal requirements are met.

## 6.1 Settings

Before the verification and sealing perform the following steps:

- 1. Verify the menu settings meet the local weights and measures regulations.
- 2. Perform a calibration as explained in Section 5.
- 3. Set the position of the security switch as shown in Section 6.3.

**Note:** When the security switch is set on the following menu settings cannot be changed: calibration, setup, mode, unit and lockout. For more details, see Section 5.3.15.

## 6.2 Verification

The local weights and measures official or authorized service agent must perform the verification procedure.

## 6.3 Securing the Menu

A slide switch is used to secure the Lock menu settings. When the switch is set to the On position, the Lock menu settings may be viewed but not changed. This switch is located behind the Base.

Set the position of the switch to ON by sliding the external Lock Switch to LOCKED as shown in the figure below.



**Note:** This switch is also used in conjunction with the Legal for Trade menu item. When the Legal for Trade menu is set to ON, the switch must be set to the On position to prevent calibration and changes to metrologically significant settings.

## 6.4 Sealing Access to the Balance Settings

The local weights and measures official or authorized service agent must apply a security seal to prevent tampering with the settings. Refer to the illustrations below for the sealing methods.



Un-locked

Locked with Paper Seal

Locked with Wire Seal

## 7.Printing

## 7.1 Connecting, Configuring and Testing the Printer / Computer Interface

Use the built-in RS-232 Port to connect either to a computer or a printer. If connecting to a computer, use HyperTerminal or similar software like SPDC described below.

(Find HyperTerminal under Accessories/Communications in Windows XP.)

Connect to the computer with a standard (straight-through) serial cable.

Choose **New Connection**, "connect using" COM1 (or available COM port).

Select Baud=9600; Parity=8 None; Stop=1; Handshaking=None. Click OK.

Choose Properties/Settings, then ASCII Setup. Check boxes as illustrated: (Send line ends...; Echo typed characters...; Wrap lines...)

Use RS232 Interface Commands (Section 9.6.1) to control the balance from a PC.

#### SPDC Software

Serial Port Data Collection V1.5.0.6

Export File Type: Excel

Balance ID: B123456789 Balance Type: AX324 Balance Name: Adventure User Name: Project M

eighing 200.0325 g inimum Weight 0.0000 g

Balance Type: Adventurer-AX

Export File Path: C:\Users\wu-55\Desktop\New Microsoft Excel Worksheetxlsx

Stop

The Serial Port Data Collection / SPDC software is provided by Ohaus and can be used on operating systems that do not have the HyperTerminal software mentioned above. SPDC software can preliminarily collect and transfer the data to Microsoft files (such as Excel, Word, etc.).

Choose the export file type and export file path and then press Run as shown below.

Clear

X

**Note:** The latest SPDC software support English and Chinese language and can be downloaded from the Ohaus' website. For more information, refer to the *SPDC Data Collection Instruction Manual*.



## 7.2 Output Format

The Result Data, and G/N/T data, is output in the following format.

Field:	Label <sup>1</sup>	Space <sup>2</sup>	Weight <sup>3</sup>	Space <sup>2</sup>	Unit <sup>4</sup>	Space	Stability <sup>5</sup>	Space	G/N <sup>6</sup>	Space	Term. Characters <sup>7</sup>
Length:		1	11	1	5	1	<u>≤</u> 1	≤ <b>1</b>	≤ <b>3</b>	0	<u>≤</u> 8

Note:

- 1. The length of the label field is not fixed.
- 2. Each field is followed by a single delimiting space (ASCII 32).
- 3. The Weight field is 11 right justified characters. If the value is negative, the '-' character is located at the immediate left of the most significant digit.
- 4. The Unit field contains the unit of measure abbreviation up to 5 characters, right justified.
- 5. The Stability field contains the "?" character if the weight reading is not stable. The Stability field and the following Space field are omitted if the weight reading is stable.
- 6. The G/N field contains the net or gross indication. For net weights, the field contains "N". For gross weights, the field contains "G".
- 7. The Termination Characters field contains CRLF, Four CRLF or Form Feed (ASCII 12), depending on the LINE FEED menu setting.
- 8. When Numeric Only is set On, only the Weight Field is printed, left-aligned.

## 7.3 Printout Examples

Examples for each Application are shown with all items turned **ON** in the **Print** menu. The default values for **Header** lines 1-5 are also shown.

#### **BASIC WEIGHING**

Header 1 Header 2 Header 3 Header 4 Header 5 07/19/2017 17:56:23 Balance ID: B234567890 Balance Name: PX5202 User Name: Project Name: Weighing					
49.98 Gross:	g 49.98	g G			
Net: Tare:	49.98 0.00	g N g T			
Signature: Verified By					

#### **BATCH WEIGHING**

07/19/2017 17:56:23 Balance ID: B234567890 Balance Name: PX224 User Name: Project Name: Weighing Start Time: End Time:
Sample Data (g) 1: 5.2403 g 2: 6.2404 g 3: 7.0000 g 4: 8.2404 g 5: 8.2404 g 6: 9.2404 g 7: 11.2404 g 8: 22.2404 g 9: 24.2404 g 10: 25.2404 g
Signature: Verified By:

#### PART COUNTING

Header 1 Header 2 Header 3 Header 4 Header 5 07/19/2017 17:57:19 Balance ID: B234567890 Balance Name: PX5202 User Name: Project Name: Parts Counting Quantity: 4999 PCS Gross: 49.99 g G Net: 49.99 g N Tare: 0.00 g T APW: 0.010 g Sample Size: 10 PCS
Signature: Verified By:

#### **DYNAMIC WEIGHING**

#### **PERCENT WEIGHING**

Header 1 Header 2 Header 3 Header 4 Header 5 07/19/2017 17:57:19 Balance ID: B234567890 Balance Name: PX223/E User Name: Project Name: Percent Weighing Percentage: 10.156 % N Gross: 23.361 g G Net: 10.156 g N Tare: 13.205 g T Reference weight: 100.000 g
Signature: Verified By:

#### DENSITY

(Density Type=Solid, auxiliary liquid=water,porous material=on)

Header 1 Header 2 Header 3 Header 4 Header 5 07/19/2017 18:03:23 Balance ID: B234567890 Balance Name: PX5202 User Name: Project Name: Density Density: 0.0345 g/cm<sup>3</sup> 49.99 g G Gross: 49.99 g N Net: gТ Tare: 0.00 Oiled Weight: 199.89 g Weight in liquid: 49.98 g Auxiliary liquid: Water liquid density: 0.9982 g/cm<sup>3</sup> Temp.: 20.0 ℃ Porous: On Oil density: 0.8000 g/cm<sup>3</sup> Dry Weight: 5.00 g Signature:

Verified By:

#### FORMULATION

Header 1 Header 2 Header 3 Header 4 Header 5 12/19/2022 17:56:23 Balance ID: B234567890 Balance Name: PX224 User Name: Project Name: Formulation Com. Total: 81.8953 g Total weight: 81.8953 g Gross: 81.8921 g G g N Net: 81.7746 Tare: 0.1175 g T -----Sample Data (g)-----Item1: 0.1173 g Item2: 81.7780 g Signature: Verified By:

#### DENSITY

(Density Type=liquid, sinker volume=10ml)

Header 1 Header 2 Header 3 Header 4 Header 5 07/19/2017 18:05:17 Balance ID: B234567890 Balance Name: PX5202 User Name: Project Name: Density Density: 14.9820 g/cm <sup>3</sup>
Gross: 49.98 g G
Net: 49.98 g N
Tare: 0.00 g T Weight in air: 199.88 g
Weight in liquid: 50.05 g
Sinker Volume: 10.0 ml
Signature:
Verified By:

#### INTERNAL CALIBRATION

-OHAUS- 07/26/2017 05:16:53 Balance ID: Balance Name: PX2202 User Name: Project Name: Internal Calibration Calibration is done. Difference weight: 0.00 g
Signature: Verified By:

#### **SPAN CALIBRATION**

-OHAUS- 03/19/2000 04:51:46
Balance ID:
Balance Name: PX2202ZH/E
User Name:
Project Name:
Span Calibration
Calibration is done.
Reference weight: 2000.00 g
Actual weight: 2000.22 g
Difference weight: 0.22 g
Weight ID:
•

Signature: \_\_\_\_\_ Verified By: \_\_\_\_\_

#### LINEARITY CALIBRATION

-OHAUS- 01/01/2000 17:30:47 Balance ID: Balance Name: PX5202M User Name: Project Name: Linearity Calibration Calibration is done.
Signature: Verified By:

# 8. MAINTENANCE

## 8.1 Calibration

Periodically verify calibration by placing an accurate weight on the balance and viewing the result. If calibration is required, refer to section 5.2 for instructions.

## 8.2 Cleaning



**WARNING:** Disconnect the balance from the power supply before cleaning. Make sure that no liquid enters the interior of the balance.

Clean the balance at regular intervals.

Housing surfaces may be cleaned with a lint-free cloth slightly dampened with water or a mild cleaning agent.



Glass surfaces may be cleaned with a commercial glass cleaner.

Attention: Do not use solvents, harsh chemicals, ammonia or abrasive cleaning agents.

## 8.3 Troubleshooting

Symptom / Display	Possible Cause	Remedy
Cannot change menu settings Menu is locked	The sub-menu is locked.	Unlock the sub-menu in Lockout Menu.
Certain sub-menu is hidden.	This is an approved model, which requests to block certain sub-menu.	Setup the balance before you turn on the Legal for Trade setting.
0.0000 g Low ref. weight	The average piece weight of the sample is too small (less than 0.1d) in Parts Counting mode.	Recaluate the APW value. If error persists, please use a different sample.
0.0000 g Invalid	The reference weight on the pan is too small (less than 100d) in Percent Weighing mode.	Put more samples on the pan.
g Timeout	The environment is not stable.	Move balance to a suitable location.
	The environment is not stable.	Move balance to a suitable location and calibrate again.
Calibration fail	Incorrect calibration masses are used.	Use calibration masses to calibrate accodrding to the correct calibration points in the specification table in the instruction manual.
	System error	If error persists, please contact OHAUS service (www.ohaus.com - More - Contact Us)

#### TABLE 8-1. TROUBLESHOOTING

Symptom / Display	Possible Cause	Remedy		
	A wrong weighing pan is used when power on.	Use OHAUS original weighing pan before power on.		
Over init. range	The load on the pan is over the initial weight setting.	Remove the load from the pan before power on.		
	A wrong weighing pan is used when power on.	Use OHAUS original weighing pan before power on.		
Under init. range	The pan is not installed when power on.	Install the weighing pan before power on.		
Error 8.3 Over load	The weight on the pan is too heavy.	Reduce sample size until the weight is within the weighing capacity.		
Error 8.4 Under load	The pan is not properly installed.	Install the weiging pan properly		
IDNR error	System error	Please contact OHAUS service (www.ohaus.com - More - Contact Us)		
Service	System error	Please contact OHAUS service (www.ohaus.com - More - Contact Us)		
Error 2.0 Error 9.5 Error 5.3	System error	Disconnect the power and restart. If error persists, please contact OHAUS service (www.ohaus.com - More - Contact Us)		

## 8.4 Service Information

If the troubleshooting section does not resolve your problem, contact an Authorized Ohaus Service Agent. Please visit our website www.ohaus.com to locate the Ohaus office nearest you.

## 9. TECHNICAL DATA

## 9.1 Specifications

#### Ambient conditions

- Indoor use only
- Altitude: Up to 2000 m
- Specified Temperature range: 10°C to 30°C
- Humidity: maximum relative humidity 80% for temperatures up to 30°C, decreasing linearly to 50% relative humidity at 40°C
- Operability is assured at ambient temperatures between 5°C and 40°C
- Mains supply voltage fluctuations: up to ±10% of the nominal voltage
- Installation category II
- Pollution degree: 2
- Supply voltage: 12V=0.5A

#### **Materials**

- Bottom Housing: Die-cast Aluminum, Painted
- Top Housing: Plastic (HIPS)
- Weighing Platforms: Stainless steel
- Draft Shield: Glass, plastic (HIPS)
- Feet: Plastic (ABS)

	DV05++	-		-	DY404	DV004	
InCal Model	PX85**	PX125D**	PX225D**	PX84	PX124	PX224	
ExCal Model Maximum Capacity (g)				PX84/E	PX124/E	PX224/E	
(Fine range/Full range)	82	52/120	82/220	82	120	220	
Readability d, Fine Range (mg)	0.01	0.01	0.01	/	1	/	
Readability d, Full Range (mg)	0.01	0.1	0.1	0.1	0.1	0.1	
Repeatability (sd.) , ≤5% of Full Load (mg)	0.01	0.01	0.01	0.08	0.08	0.08	
Repeatability (sd.), 5% of Full Load to Fine Range Max (mg)	0.02	0.02	0.02	/	1	1	
Repeatability (sd. ), Fine Range Max to Full Range	0.02	0.1	0.1	0.1	0.1	0.1	
Linearity Deviation, Typical (mg)	± 0.06	± 0.06	± 0.06	± 0.06	± 0.06	± 0.06	
Linearity Deviation (mg)	± 0.1	± 0.1	± 0.1	± 0.2	± 0.2	± 0.2	
Stabilization Time Typical (s)	10	10	10	3	3	3	
Sensitivity Temperature Drift (PPM/K)	±2	±2	±2	±2	±2	±2	
Typical Minimum Weight USP (USP K=2,U=0.10%)	20 mg	20 mg	20 mg	160 mg	160 mg	160 mg	
Optimized Minimum -Weight (g) (USP, u=0.10%, k=2) SRP≤0.41d*	8.2 mg	8.2 mg	8.2 mg	82 mg	82 mg	82 mg	
Units	Gram, Milligram, Carat, Ounce, Ounce Troy, Grain, Pennyweight, Momme, Mesghal, Tical (MM), Tola (India), Baht, 1 Custom unit Kilogram, Pound, Baht						
Applications	Basic Weigh	ning, Parts Counti	ng, Percent Weig	hing, Dynamic Wei	ghing, Density Deter	mination, Formulation	
Platform Size (diameter, mm)	80	80	80	90	90	90	
Span Calibration Points (g)	50, 80	50, 100	100, 200	50, 80	50, 100	100, 200	
Linearity Calibration Points (g)	0, 40, 80	0, 50, 100	0, 100, 200	0, 40, 80	0, 50, 100	0, 100, 200	
Tare Range			To ca	pacity by subtractio	n		
Power Supply		Р		240V ~ 200mA 50-6 output: 12 VDC 0.5			
Assembled Dimensions (W x D x H) (mm)		209 x 321 x 309					
Communication				RS232, USB			
Operating Temperature Range	Operating conditions for ordinary lab application: +10°C to 30°C (operability guaranteed between +5°C and 40°C).						
Storage Temperature Range		•		humidity 80 % for te to 50% relative hu	emperatures up to 30 midity at 40°C	°C,	
Storage Conditions		-10°C	C to 60°C, humidi	ty 10% to 90%, with	nout condensation		
Net Weight				10 lb / 4.5 kg			
Shipping Weight				15.4 lb / 7 kg			
Shipping Dimensions (W x D x H) (mm)			5	507 x 387 x 531			
Note:	I						

#### TABLE 9-1. SPECIFICATIONS

Note:

\*SRP refers to the standard deviation for n replicate weightings ( $n \ge 10$ ).

\*\* Automatic Calibration models

	DV4CO	DV000	DV000	DV 400	DVC00	DVCOO	DV000	DV4C00	DV0000	
InCal Model ExCal Model	PX163	PX223 PX223/E	PX323 PX323/E	PX423 PX423/E	PX523 PX523/E	PX623 PX623/E	PX822 PX822/E	PX1602 PX1602/E	PX2202 PX2202/E	
	PX163/E	220		420		620				
Capacity (g) Readability d (g)	160		320		520		820 0.01	1600	2200	
	0.001	0.001	0.001	0.001	0.001	0.001	0.01	0.01	0.01	
Repeatability (sd.), ≤5% of Full Load (g)	0.0008	0.0008	0.0008	0.0008	0.0008	0.0008	0.008	0.008	0.008	
Repeatability (sd.), 5% of										
Full Load to Full Range	0.001	0.001	0.001	0.001	0.001	0.001	0.01	0.01	0.01	
(g)	0.001	0.001	0.001	0.001	0.001	0.001	0.01	0.01	0.01	
Linearity Deviation,										
Typical (g)	±0.0006	±0.0006	±0.0006	±0.0006	±0.0006	±0.0006	±0.006	±0.006	±0.006	
Linearity Deviation (g)	±0.002	±0.002	±0.002	±0.002	±0.002	±0.002	±0.02	±0.02	±0.02	
Stabilization Time	0	0	0	0	0	0	4	4	4	
Typical (s)	2	2	2	2	2	2	1	1	1	
Sensitivity Temperature Drift (PPM/K)	±3	±3	±3	±3	±3	±3	±3	±3	±3	
Typical Minimum Weight										
USP	1.6 g	1.6 g	1.6 g	1.6 g	1.6 g	1.6 g	16 g	16 g	16 g	
(USP K=2,U=0.10%)										
Optimized Minimum -										
Weight (g)	0.82g	0.82g	0.82g	0.82g	0.82g	0.82g	8.2 g	8.2 g	8.2 g	
(USP, u=0.10%, k=2)	5						5	5	5	
SRP≤0.41d*							One of Kill		ten Deved	
	Gram M	illigram, Carat,	Newton Our		ov Grain Pen	nyweight		ogram, Carat, New Ince Troy, Grain, P		
Units		•			•		Momme, Mesghal, Hong Kong Tael,			
onno	100000000000000000000000000000000000000	• •	• •	ael, Taiwan Tael, Tical (MM), Tola (India), ogram, Pound, Baht			Singapore Tael, Taiwan Tael, Tical (MM),			
				J - ,,				ndia), Baht, 1 Cus		
Applications	Ba	asic Weighing.	Parts Countir	na. Percent W	eighing. Dyna	mic Weighing.		rmination, Formula		
Platform Size (diameter,										
mm)	120	120	120	120	120	120	180	180	180	
Span Calibration Points	100, 150,					300, 500,		1000 1500		
(g)	160, 100,	100, 200	200, 300	200, 400	300, 500	600	500, 800	1000, 1500,	1000, 2000	
Linearity Calibration								1600	0, 1000,	
Points (g)	0, 80, 160	0, 100, 200	0, 150, 300	0, 200, 400	0, 250, 500	0, 300, 600	0, 400, 800	0, 800, 1600	2000	
Tare Range				I To	capacity by su	ubtraction				
-			P			mA 50-60Hz 1	2_18\/A			
Power Supply					ver output: 12		2-1004			
Assembled Dimensions										
(W x D x H) (mm)	209 x 321 x 309 209 x 321 x 98									
Communication	RS232, USB									
Operating Temperature	Opera	ating condition	s for ordinarv	lab application	n: +10°C to 30	°C (operability	/ guaranteed l	between +5°C and	40°C).	
Range		and contained		••		· · ·	•			
Storage Temperature Range		Humidity: maximum relative humidity 80% for temperatures up to 30°C, decreasing linearly to 50% relative humidity at 40°C								
<u>,</u>										
Storage Conditions	-10°C to 60°C, humidity 10% to 90%, without condensation									
Net Weight	10 lb / 4.5 kg							7.7 lb / 3.5 kg		
Shipping Weight	15.4 lb / 7 kg 11 lb / 5 kg									
Shipping Dimensions			507 x 3	87 x 531				550 x 385 x 291		
(W x D x H) (mm)			007 X 00					500 A 000 A 201		
	i									

#### TABLE 9-2. SPECIFICATIONS (continued)

Note: \*SRP refers to the standard deviation for n replicate weightings (n≥10).

InCal Model	PX3202	PX4202	PX5202	PX6202	PX2201	PX4201			PX12001
ExCal Model	PX3202/E	PX4202/E	PX5202/E	PX6202/E	PX2201/E	PX4201/E	PX6201/E	PX8201/E	PX12001/E
Capacity (g)	3200	4200	5200	6200	2200	4200	6200	8200	12000
Readability d (g)	0.01	0.01	0.01	0.01	0.1	0.1	0.1	0.1	0.1
Repeatability (sd.),									
≤5% of Full Load (g)	0.008	0.008	0.008	0.008	0.08	0.08	0.08	0.08	0.08
Repeatability (sd.), 5%									
of Full Load to Full	0.01	0.01	0.01	0.01	0.1	0.1	0.1	0.1	0.1
Range (g)									
Linearity Deviation,	±0.006	±0.006	±0.006	±0.006	±0.06	±0.06	±0.06	±0.06	±0.06
Typical (g)									
Linearity Deviation (g)	±0.02	±0.02	±0.02	±0.02	±0.2	±0.2	±0.2	±0.2	±0.2
Stabilization Time	1	1	1	1	1	1	1	1	1
Typical (s)									
Sensitivity Temperature	±3	±3	±3	±3	±5	±5	±5	±5	±5
Drift (PPM/K) Typical Minimum									
Weight USP	16 g	16 g	16 g	16 g	160 g	160 g	160 g	160 g	160 g
(USP K=2,U=0.10%)	10 9	iog	io g	10 9	100 g				
Optimized Minimum -									
Weight (g)	0.0-	0.0-	0.0-	0.0-	00-	00-	00-	00-	00-
(USP, u=0.10%, k=2)	8.2g	8.2g	8.2g	8.2g	82g	82g	82g	82g	82g
SRP≤0.41d*									
	Gram, Kilo	ogram. Carat	. Newton. Pou	und. Ounce. (	Dunce Trov. (	Grain, Pennyw	veight. Momm	e. Mesahal.	Hona Kona
Units	0.0,								
		Tael, Singapore Tael, Taiwan Tael, Tical (MM), Tola (India), 1 Custom unit							
Applications			-			c Weighing, I	-		
Platform Size (mm)	Ø180	Ø180	Ø180	Ø180	Ø180	Ø180	Ø180	Ø180	193 x 248
Span Calibration Points	2000,	2000,						5000,	3kg, 5kg,
(g)	3000	4000	3000, 5000	5000, 6000	1000, 2000	2000, 4000	5000, 6000	8000	7kg, 9kg,
			0.0500	0.2000	0 1000	0.0000	0.2000		11kg, 12kg
Linearity Calibration Points (g)	0, 1500, 3000	0, 2000, 4000	0, 2500, 5000	0, 3000, 6000	0, 1000, 2000	0, 2000, 4000	0, 3000, 6000	0, 4000, 8000	0, 6000, 12000
Tare Range	3000	4000	5000				0000	0000	12000
Tale Rallye					pacity by sub				
Power Supply			Powe	•		A 50-60Hz 12	-18VA		
		Power output: 12 VDC 0.5A							
Assembled Dimensions		209 x 321						209 x 321	
(W x D x H) (mm)	209 x 321 x 98								
Communication	RS232, USB								
Operating Temperature	Operating conditions for ordinary lab application: +10°C to 30°C (operability guaranteed between +5°C and 40°C).								
Range	Operating		,						<i>aliu</i> 40 C).
Storage Temperature		Hu				6 for temperat		°C,	
Range	decreasing linearly to 50% relative humidity at 40°C								
Storage Conditions	-10°C to 60°C, humidity 10% to 90%, without condensation								
Net Weight	7.7 lb / 3.5 kg								
Shipping Weight					11 lb / 5 kg				
Shipping Dimensions					50 v 305 v 0	01			
$(W \times D \times H)$ (mm)					50 x 385 x 29	וכ			

#### TABLE 9-3. SPECIFICATIONS (continued)

#### Note:

\*SRP refers to the standard deviation for n replicate weightings (n $\ge$ 10).

InCal Approval Model	PX125DM**	PX225DM**	PX85M**	<b>• • • • • • • • • •</b>	, РХ224М	PX323M	PX523M	PX623M
Maximum Capacity	-							
(Fine range/Full range) (g)	52/120	82/220	82	120	220	320	520	620
Readability d, Fine Range (g)	0.00001	0.00001	0.00001	1	1	1	1	/
Readability d, Full Range (g)	0.0001	0.0001	0.00001	0.0001	0.0001	0.001	0.001	0.001
Verification Interval e (g)	0.001	0.001	0.001	0.001	0.001	0.01	0.01	0.01
Class	I	I	l	I	_			
Repeatability (sd.) , ≤5% of Full Load (g)	0.00001	0.00001	0.00001	0.00008	0.00008	0.0008	0.0008	0.0008
Repeatability (sd.), 5% of Full Load to Fine Range Max (g)	0.00002	0.00002	0.00002	1	/	1	1	/
Repeatability (sd. ) , Fine Range Max to Full Range (g)	0.0001	0.0001	0.00002	0.0001	0.0001	0.001	0.001	0.001
Linearity Deviation, Typical (g)	± 0.00006	± 0.00006	± 0.00006	± 0.00006	± 0.00006	± 0.0006	± 0.0006	± 0.0006
Linearity Deviation (g)	± 0.0001	± 0.0001	± 0.0001	± 0.0002	± 0.0002	± 0.002	± 0.002	± 0.002
Stabilization Time Typical (s)	10	10	10	3	3	2	2	2
Sensitivity temperature drift (PPM/K)	±2	±2	±2	±2	±2	±3	±3	±3
Typical Minimum Weight USP (USP K=2,U=0.10%)	20 mg	20 mg	20 mg	160 mg	160 mg	1.6 g	1.6 g	1.6 g
Optimized Minimum -Weight (g) (USP, u=0.10%, k=2) SRP ≤ 0.41d*	8.2 mg	8.2 mg	8.2 mg	82 mg	82 mg	0.82 g	0.82 g	0.82 g
Units				g, mg , c	zt			
Applications	Basic Weighing	, Parts Counting	, Percent Wei	ghing, Dyna	mic Weighing	, Density Dete	ermination, Fo	rmulation
Platform Size (diameter, mm)	80	80	80	90	90	120	120	120
Span Calibration Points (g)	50, 100	100, 200	50, 80	50, 100	100, 200	200, 300	300, 500	300, 500, 600
Linearity Calibration Points (g)	0, 50, 100	0. 100, 200	0, 40, 80	0, 50, 100	0, 100, 200	0, 150, 300	0, 250, 500	0, 300, 600
Tare Range				apacity by si				
Power Supply		Pov		-240V ~ 200 <sup>-</sup> output: 12	mA 50-60Hz 2 VDC 0.5A	12-18VA		
Assembled Dimensions (W x D x H) (mm)				209 x 321 x	309			
Communication				RS232, U	SB			
Operating Temperature Range	Operating conditions for ordinary lab application: +10°C to 30°C (operability guaranteed between +5°C and 40°C).							
Storage Temperature Range	Humidity: maximum relative humidity 80% for temperatures up to 30°C, decreasing linearly to 50% relative humidity at 40°C							
Storage Conditions	-10°C to 60°C, humidity 10% to 90%, without condensation							
Net Weight				10 lb / 4.5	kg			
Shipping Weight				15.4 lb / 7	kg			
Shipping Dimensions (W x D x H) (mm)				507 x 387 x				

#### TABLE 9-4. SPECIFICATIONS (continued)

Note:

\*SRP refers to the standard deviation for n replicate weightings ( $n \ge 10$ ).

\*\* Automatic Calibration models

InCal Approval Model	PX3202M	PX5202M	PX6202M	PX4201M				
Capacity (g)	3200	5200	6200	4200				
Readability d (g)	0.01	0.01	0.01	0.1				
Verification Interval e (g)	0.1	0.1	0.1	0.1				
Class								
Repeatability (sd.) , ≤5% of Full Load (g)	0.008	0.008	0.008	0.08				
Repeatability (sd.), 5% of Full Load to Full Range (g)	0.01	0.01	0.01	0.1				
Linearity Deviation, Typical (g)	± 0.006	± 0.006	± 0.006	± 0.06				
Linearity Deviation (g)	± 0.02	± 0.02	± 0.02	± 0.2				
Stabilization Time Typical (s)	1	1	1	1				
Sensitivity temperature drift (PPM/K)	±3	±3	±3	±5				
Typical Minimum Weight USP (USP K=2,U=0.10%)	16 g	16 g	16 g	160 g				
Optimized Minimum -Weight (g) (USP, u=0.10%, k=2) SRP $\leq$ 0.41d*	8.2 g	8.2 g	8.2 g	82 g				
Units	g, kg , ct							
Applications		s Counting, Percent Weigh						
Platform Size (diameter, mm)	180	180	180	180				
Span Calibration Points (g)	2000, 3000	3000, 5000	5000, 6000	2000, 4000				
Linearity Calibration Points (g)	0, 1500, 3000	0, 2500, 5000	0, 3000, 6000	0, 2000, 4000				
Tare Range		To capacity b						
Power Supply	Power input: 100-240V ~ 200mA 50-60Hz 12-18VA Power output: 12 VDC 0.5A							
Assembled Dimensions (W x D x H) (mm)		209 x 3	21 x 98					
Communication	RS232, USB							
Operating Temperature Range	Operating conditions for ordinary lab application: +10°C to 30°C (operability guaranteed between +5°C and 40°C).							
Storage Temperature Range	Humidity: maximum relative humidity 80% for temperatures up to 30°C, decreasing linearly to 50% relative humidity at 40°C							
Storage Conditions	-10	°C to 60°C, humidity 10%		tion				
Net Weight		7.7 lb /						
Shipping Weight		11 lb	/ 5 kg					
Shipping Dimensions (W x D x H) (mm)		550 x 38	550 x 385 x 291					


#### TABLE 9-5. SPECIFICATIONS (continued)


Note:

\*SRP refers to the standard deviation for n replicate weightings (n $\ge$ 10).

## 9.2 Drawings and Dimensions


Fully assembled dimensions









0.001 g / 0.0001 g model







0.01 g / 0.1 g model






Figure 9-3 12 l

12 kg x 0.1 g model

## 9.3 Accessories

DESCRIPTION	PART NUMBER
Auxiliary display, AD7-RS	30472064
Density Kit	80253384
Calibrated Sinker for Liquid Density Determination	83034024
USB Interface Cable	83021085
Security Device	80850043
RS232 Cable (25 pin)	80500524
RS232 Cable (9 pin)	80500525

DESCRIPTION	PART NUMBER
Dust Cover	30093334
In-use Cover	30372546
Printer SF40A	30064202 (EU); 30064203 (AM)
Power Adapter for Balance	46001724

## 9.4 Communication

### 9.4.1 Interface Commands

Commands listed in the following table will be acknowledged by the balance.

Command Characters	Function
IP	Immediate Print of displayed weight (stable or unstable).
Р	Print displayed weight (stable or unstable).
CP	Continuous Print.
SP	Print on Stability.
Н	Enter Print Header Lines
Z	Same as pressing Zero Key
Т	Same as pressing Tare Key.
xT***	Establish a preset Tare value in displayed unit. X = preset tare value. Sending 0T clears tare
	(if allowed).
PT	Prints Tare weight stored in memory.
ON	Brings out of Standby
OFF	Goes to Standby.
С	Begin Span Calibration
IC	Begin Internal Calibration, same as trigger from calibration menu.
AC	Abort Calibration. Attention: when LFT ON, the operation is not allowed.
PSN	Print Serial Number.
PV	Print terminal software version, base software version and LFT ON (if LFT is set ON).
x#	Set Counting APW (x) in grams. (must have APW stored)
P#	Print Counting application APW.
x%	Set Percent application reference weight (x) in grams. (must have reference weight stored)
P%	Print Percent application reference weight.
xRL	0 = disable response; 1 = enable response. This command only controls the "OK!" response.
хT	Pre-tare the container weight (x) in grams.

#### 9.4.2 RS232 (DB9) Pin Connections

Diagram	Туре	Description		
	Interface type	Voltage interface conforming to EIA RS-232C/DIN 66020 (CCITT V24/V.28)		
DATA	Max. cable length	15 m		
RxD	Signal level	Output:		
		+5 V +15 V (RL = 3 – 7kΩ)		
TUD CIT		-5 V15 V (RL = 3 - 7 kΩ)		
GND RT_CTL		Input:		
1     -		+3 V +25 V		
		-3 V25 V		
	Connector	Sub-D, 9-pole, female		
	Operating mode	Full duplex		
	Transmission mode	Bit-serial, asynchronous		
SHAKE	Transmission code	ASCII		
	Baud rates	1200, 2400, 4800, 9600, 19200, 38400 (firmware selectable)		
	Bits/parity	7-bit/even, 7-bit/odd, 7-bit/none, 8-bit/none (firmware selectable)		
	Stop bits	Stop bit 1, 2		
	Handshake	None, XON/XOFF, RTS/CTS (selectable)		
	End-of-line	Not selectable		

#### 9.4.3 USB Interface

The Ohaus USB Interface is a unique solution to the problem of connecting a balance to a computer using a Universal Serial Bus (USB). USB devices are categorized into classes such as disk drives, digital cameras, printers, etc. Balances do not have a commonly used class so the Ohaus USB interface uses a generic interface based on the RS232 serial standard.

Data sent from the balance to a computer is in USB format. The USB data is directed to a *virtual port*. This port then appears as an RS232 port to the application program.

When sending a command from a computer to the balance, the application program sends a command to the *virtual port* as if it were an RS232 port. The computer then directs the command from the *virtual port* to the computers USB connector where the balance is connected. The port receives the USB signal and reacts to the command.

#### **System Requirements**

- PC running Windows 98<sup>®</sup>, Windows 98SE<sup>®</sup>, Windows ME<sup>®</sup>, Windows 2000<sup>®</sup>, Windows XP<sup>®</sup>, Windows 7<sup>®</sup> or Windows 8<sup>®</sup> (32-bit) or Windows 10<sup>®</sup>.
- Available USB port (Type A, 4-pin, female)

#### 9.4.4 USB Connection

The balance's USB port terminates with a 4-pin, female, USB Type B connector.

A USB Cable (type B/male to type A/male) is required (not supplied).

- 1. Ensure that the balance is powered on and working properly.
- 2. Power on the computer and verify that its USB port is enabled and working properly.
- 3. Plug the cable's USB connectors into the computer's USB port and the balance's USB port. Windows® should detect a USB device and the New Hardware Wizard will be initialized.

#### **Download from Ohaus' Website**

- 1. The New Hardware Wizard guides you through the required steps to select the driver that is located on the website.
- 2.After clicking Finish, the virtual port should be ready for use.

Windows<sup>®</sup> typically adds the virtual port in sequence after the highest number COM port. For example, on PC's equipped with up to 4 COM ports, the virtual port will be COM5.

When using the USB interface with programs that limit the number of COM port designations (e.g. Ohaus MassTracker allows only COM1, 2, 3, & 4), it may be necessary to assign one of these port numbers to the new virtual port.



Example of Windows XP Hardware Wizard

This can be done in the Port Settings of the Device Manager utility, found in the Windows Control Panel.

#### **USB INPUT**

The balance will respond to various commands sent via the interface adapter.

Terminate the following commands when with a [CR] or [CRLF]

#### **PX Commands**

- P same as pressing Print
- SP print stable weight only
- **IP** immediate print of displayed weight (stable or unstable)
- **CP** Continuous print of weights
- T same as pressing Tare
- **Z** same as pressing Zero
- **PV** print software version
- **xT** establish a preset Tare value in displayed unit. X = preset tare value. Sending 0T clears tare (if allowed).

#### **Auto-Print Operation**

Once Auto-Print is activated in the menu, the balance will send data as required. If there is data in the print buffer the printer will finish printing this data.

## **10. SOFTWARE UPDATES**

Ohaus is continuously improving its balance software. To obtain the latest release, please contact your Authorized Ohaus Dealer or Ohaus Corporation.

# **11. COMPLIANCE**

Compliance to the following standards is indicated by the corresponding mark on the product.

Mark	Standard
CE	This product complies with the applicable harmonized standards of EU Directives 2011/65/EU (RoHS), 2014/30/EU (EMC), 2014/35/EU (LVD) and 2014/31/EU (NAWI). The EU Declaration of Conformity is available online at www.ohaus.com/ce.
X	This product complies with the EU Directive 2012/19/EU (WEEE) and 2006/66/EC (Batteries). Please dispose of this product in accordance with local regulations at the collecting point specified for electrical and electronic equipment. For disposal instructions in Europe, refer to www.ohaus.com/weee.
UK CA	This product complies with the applicable statutory standards of the Restriction of the Use of Certain Hazardous Substances in Electrical and Electronic Equipment Regulations 2012, UK Electromagnetic Compatibility Regulations 2016, Electrical Equipment (Safety) Regulations 2016 and Non-Automatic Weighing Instruments Regulations 2016. The UK Declaration of Conformity is available online at www.ohaus.com/uk-declarations.
	EN 61326-1
C <sub>MC173467</sub> ® US	CAN/CSA-C22.2 No. 61010-1 UL Std. No. 61010-1

#### Important notice for PX/PXP/PJX/PR...M verified weighing instruments in the EU and UK

When the instrument is used in trade or a legally controlled application it must be set up, verified and sealed in accordance with local weights and measures regulations. It is the responsibility of the purchaser to ensure that all pertinent legal requirements are met.

Weighing Instruments verified at the place of manufacture bear the following supplementary metrology marking on the descriptive plate.





Weighing Instruments to be verified in two stages have no supplementary metrology marking on the descriptive plate. The second stage of conformity assessment must be carried out by the applicable weights and measures authorities.

If national regulations limit the validity period of the verification, the user of the weighing instrument must strictly observe the re-verification period and inform the weights and measures authorities.

As verification requirements vary by jurisdiction, the purchaser should contact their local weights and measures office if they are not familiar with the requirements.

#### ISED Canada Compliance Statement:

This Class B digital apparatus complies with Canadian ICES-003.

#### **ISO 9001 Registration**

The management system governing the production of this product is ISO 9001 certified.

#### FCC Supplier Declaration of Conformity

Unintentional Radiator per 47CFR Part B Trade Name: OHAUS CORPORATION Model or Family identification: PX/PXP/PJX/PR

#### Issuing Party that Assembled the Product:

Ohaus Instruments (Changzhou) Co., Ltd. Building C, No. 6 Zhengqiang Road, Xuejia Town, Xinbei District, Changzhou Jiangsu 213022 China Phone: +86 519 85287270

#### **Responsible Party – U.S. Contact Information:**

Ohaus Corporation 8 Campus Drive, Suite 105 Parsippany, NJ 07054 United States Phone: +1 973 377 9000 Web: www.ohaus.com

#### **FCC Compliance Statement:**

Note: This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

-Reorient or relocate the receiving antenna.

-Increase the separation between the equipment and receiver.

-Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.

-Consult the dealer or an experienced radio/TV technician for help.

Changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment.

#### EN-55

#### LIMITED WARRANTY

Ohaus products are warranted against defects in materials and workmanship from the date of delivery through the duration of the warranty period. During the warranty period Ohaus will repair, or, at its option, replace any component(s) that proves to be defective at no charge, provided that the product is returned, freight prepaid, to Ohaus.

This warranty does not apply if the product has been damaged by accident or misuse, exposed to radioactive or corrosive materials, has foreign material penetrating to the inside of the product, or as a result of service or modification by other than Ohaus. In lieu of a properly returned warranty registration card, the warranty period shall begin on the date of shipment to the authorized dealer. No other express or implied warranty is given by Ohaus Corporation. Ohaus Corporation shall not be liable for any consequential damages.

As warranty legislation differs from state to state and country to country, please contact Ohaus or your local Ohaus dealer for further details.